

S-390 Dr. Bevans' House Princess Anne private c. 1900-1910

Dr. Bevans' house is a large tee-shaped turn of the century frame dwelling that stands in a line of contemporary buildings on the west side of South Somerset Avenue. Although the house has been moderately remodeled and converted to a dentist's office, the two-and-a-half story dwelling carries a mixture of Victorian and Colonial Revival features. The eclectic residence contributes to the uninterrupted row of period houses that characterize south Princess Anne.

## Maryland Historical Trust State Historic Sites Inventory Form

Survey No. S-390
Magi No. 2003905704
DOE \_\_yes \_\_no

1. Nan	1e (indicate pr	eferred name)		
historic				
and/or common	Dr. Bevan's House			
2. Loca	ation			
street & number	r 406 South Somerse	t Avenue		not for publication
city, town Pr	incess Anne	vicinity of	congressional district	First
	yland	county	Somerset	
3. Clas	sification			
Category  district building(s) structure site object	Ownership public private both Public Acquisition in process being considered Xnot applicable	Status _X occupied unoccupied work in progress Accessible _X yes: restricted yes: unrestricted no	Present Use agriculture _X_ commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names an	d mailing addresses	of <u>all</u> owners)
name Dr. R	ichard A. Bevan			
street & number	406 South Somerse	Avenue	telephone no	·: 651-1091
city, town Prin	ncess Anne	state	and sin and	853
		al Descriptio		
courthouse, regis	stry of deeds, etc. Some	rset Clerk of Court		liber
street & number	Somerset County Cou	irthouse		folio
city, town Prin	ncess Anne		state	MD 21853
6. Repr	resentation	in Existing	Historical Surve	ys
title				
date			federal state	county local
depository for su	rvey records			
city, town			state	

7.	Des	scri	ptio	n
		<i>,</i>	L	-

Survey No. S-390

 Condition
 Check one
 Check one

 \_\_\_ excellent
 \_\_\_ deteriorated
 \_\_\_ unaltered
 \_\_\_ x original site

 \_\_\_ good
 \_\_\_ ruins
 \_\_\_ altered
 \_\_\_ moved
 date of move

 \_\_\_ fair
 \_\_\_ unexposed

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Dr. Bevans' house is located at 406 South Somerset Avenue in the southern residential district of Princess Anne, Somerset County, Maryland. The large turn of the century frame house faces east with the principal gable oriented on a north/south axis.

Supported by a raised brick foundation, the tee-shaped frame house is sheathed with aluminum siding and covered by a steeply pitched asphalt shingle roof. Attached to the back of the main block is a two-story service wing.

The east (main) elevation is an uneven three-bay elevation with a center entrance and flanking multi-pane sash windows. Covering the first floor is a single-story enclosed porch with a double-door entrance flanked by a series of large and small multi-pane windows. The entrance bay is marked by a gabled Tuscan column porch. Unlike the first floor, the second floor retains an uneven facade with a projecting south gabled bay and two recessed northern bays. A pair of multi-pane sash windows light the second floor of the two-story bay, while a smaller pair of windows illuminate the attic. The gable is defined by a pediment. The northern two bays are marked by single multi-pane sash windows, and the roof is pierced by a gabled dormer. Two interior brick chimneys rise from the center of the house.

The north gable end of the tee-plan is covered on the first floor by the enclosed porch addition, and the second floor is defined by two multi-pane sash windows. The gable end is finished with the same pediment found on the front of the house, and the attic is lighted by a paired multi-pane sash window.

The south side of the house is an asymmetrical elevation covered on the first floor by an enclosed porch. The second floor is lighted by a combination of single and paired sash, and the roof is marked by a single gabled dormer as well as a large cross gable that tops the west bay.

The interior was not seen.

8. Significance		Survey No. S	3–390
Period         Areas of Significance          prehistoric        archeology-prehistor          1400-1499        archeology-histor          1500-1599        agriculture          1700-1799        architecture          1800-1899        commerce          X 1900-        communications	ce—Check and justify below storic community planning ric conservation economics education engineering exploration/settlement industry invention	law literature military music	science sculpture social/ humanitarian theater
Specific dates	Builder/Architect		
check: Applicable Criteria: and/or Applicable Exception:	ABCD	EFG	
Level of Significance	:nationalstate _	_local	
Prepare both a summary paragrasupport.	aph of significance and a	general statemen	t of history and

The Dr. Bevans house stands on the west side of South Somerset Avenue in a line of turn of the century frame houses that distinguish the south end of Princess Anne. Although the house has been moderately remodeled and converted into a dentist's office, the tee-plan frame house retains its general form and several period features. It also contributes to the uninterrupted row of period houses that characterize south Princess Anne.

## 9. Major Bibliographical References

Survey No. S-390

10. Geographic	cal Data		
Acreage of nominated property Quadrangle name UTM References do NOT comp			Quadrangle scale
Zone Easting No	rthing	B   Zone	Easting Northing
C		D	
Verbal boundary description a	and justification		
List all states and counties fo	or properties over	apping state or cou	
state	code	county	code
state state 11. Form Prepa	code	county	code
11. Form Prep	code	county	
11. Form Prep	code ared By Architectural	county	
11. Form Preparation Paul Touart -  organization Somerset Count	code ared By Architectural	county  Historian  cust dat	code

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.


return to:

Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438





Dr. Bevan's House S-390 Princess Anne, Somerset Co., Md. Northeast Elevation 4/86, Paul Touart, Photographer Neg./Md. Historical Trust